

Approval No: **E24 16R-060086**

ECE TYPE-APPROVAL CERTIFICATE

Communication concerning the approval granted of a type of safety belt or restraint system for adult occupants of power driven vehicles pursuant to Regulation No. 16.



Reason for extension: - N/A Restraint System (with)/three-point belt/lap belt/special type belt/fitted (with) energy absorber/retractor and 1. device for height adjustment of the upper pillar loop. 2. Trade name or mark: Hazna 3. Manufacturer's designation of the type of belt or HN-200-1 restraining system: 4. Manufacturer's Name: Danyang Hazna Vehicle Parts Co., Ltd. Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province, China. 5. If applicable, name of manufacturer's representative: N/A N/A 6. Address: 7. Submitted for approval on: 25.05.2013



Extension No: N/A



Approval No: <u>**E24 16R-060086</u>** Extension No: *N/A*</u>

8. Technical Service responsible for conducting approval tests: *TÜV Rheinland Kraftfahrt GmbH*,

Technologiezentrum Verkehrssicherheit, Typprüfstelle Fahrzeuge/Fahrzeugteile,

Am Grauen Stein, D-51105 Köln (Poll),

Germany.

9. Date of report issued by that service: **08.06.2013**

10. Number of report issued by that service: 87-R16-600/13

11. Type of device: deceleration/acceleration: **Deceleration.**

12. Approval granted/refused/extended/withdrawn for general use/for use in a particular vehicle or in particular vehicle types.

13. Position and nature of the marking: Label sewed on long end assembly.

14. Place: **Dublin**

15. Date: 26th July 2013.

16. Signature: 16.

17. Annexed to this communication is a list of documents in the approval file deposited at the administration services having delivered the approval and which can be obtained upon request.





Date of issue:

- number(s):

- date of issue:

Documentation:

- date of latest amendment:

Date of latest amendment:

Approval No: <u>E24 16R-060086</u> Extension No: *N/A*

Index to the Information Package

26th July 2013.

HN-200-1 V00

25.05.2013

N/A

23 pages

N/A

	Reason for extension/revision:	N/A
1.	Additional conditions, and advisory notes on legal alternatives.	
2.	Test report(s)	
	- numbers(s):	87-R16-600/13
	- date of issue:	08.06.2013
	- date of latest amendment:	N/A
3.	Information document	





Approval No: <u>E24 16R-060086</u> Extension No: *N/A*

Appendix: Additional conditions, and advisory notes on legal alternatives

A: Additional conditions:

- 1. The attached technical report, with any of its attachments, forms part of this Type Approval certificate.
- 2. Each type from series production shall be to the measurements specified in the attached drawings, and shall be manufactured only from the materials specified in the Approval documents.
- 3. Changes in the type are permitted only with the explicit permission of NSAI. Breaches of this requirement will lead to a withdrawal of the Type Approval, and in addition may be subject to criminal prosecution.
- 4. At regular intervals, any tests or associated checks prescribed by the applicable legislation to verify continued conformity with the approved type shall be carried out. The manufacturer shall demonstrate compliance with this by submitting to NSAI evidence of adequate arrangements and documented control plans for each type approved.
- 5. Any set of samples or test pieces showing evidence of non-conformity shall give rise to further sampling and testing and all steps shall be taken to restore conformity of production.
- 6. This Type Approval will expire when it is surrendered by the holder, or withdrawn by NSAI, or when the approved type no longer conforms to legal requirements. The recall of the Type Approval can be issued by NSAI when the conditions required for the issuing or continuation of the Type Approval are no longer current, or when the Approval holder is in breach of the duties attached to the Type Approval, or when it is established that the approved type no longer meets the requirements of traffic safety.
- 7. Changes in the company name, address or manufacturing site, as well as in any of the sales or other agents specified in the issuing of the approval must immediately be notified to NSAI.
- 8. The duties imposed by the issuing of this certificate are not transferable. The legal protection of third parties is not affected by this certificate.
- 9. When the manufacture or sale of the system, component or separate technical unit has not been started within one year of the date of issue of this certificate, then NSAI is to be informed. This requirement also applies when the manufacture or sale has been halted for more than one year, or when it ought to have been halted for more than one year. The initial commencement of manufacture or sale, or the resumption of manufacture or sale, shall then be notified to NSAI within one month of commencement or resumption.


B: Legal Options:

Any objection to the requirements set out in this certificate shall be made within one month of the date of issue. The objection shall be made, in writing, to NSAI in Dublin.



TÜV Rheinland Group Test Report No.: 87-R16-600/13

: HN-200-1 **Type**





TEST REPORT

according to ECE-Regulation

Uniform provisions concerning the approval of Safety-belts, restraint systems, child restraint systems and isofix child restraint systems for occupants of power-driven vehicles

ECE-R16

including all amendments until

Series of amendments: 06 Amendment 2

Previously granted ECE - certificate

Structure of report 0. General information

1. Test object(s) and general test information

2. Test minutes

3. Remarks concerning tested object(s)

4. Appendices

5. Statement of conformity

205 AUTI TRANSPORT DEPARTMENT page 1 of 11

TÜV Rheinland Kraftfahrt GmbH

Technologiezentrum Verkehrssicherheit Typprüfstelle Fahrzeuge/Fahrzeugteile Am Grauen Stein, D-51105 Köln (Poll)

Accreditation: NSAI-73

TÜV Rheinland Group Test Report No.: 87-R16-600/13

Type : HN-200-1

Manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.



0. General information

0.1. Make (trade name of the manufacturer)

0.2. Type

Type of safety belt : HN-200-1

Versions : ---

0.3. Category of safety belt : Lap-belt

0.4. Name and address of the manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.

Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province,

China

0.5. No. of information folder : HN-200-1 V00

date of issue : May. 25, 2013

1. Test object(s) and general test information

1.1. Test object(s)

identification number : ---

Type : HN-200-1

1.2. General test information

1.2.1. Test date : May 29, 2013 to June 7, 2013

1.2.2. Test site : Wuhu Golden Safety System Co., Ltd. (Nanjing plant) Test Lab

Industrial Zone of Zhetang Town, Lishui County, Nanjing City,

Jiangsu Province, China 211215

1.2.3. Remark : The results of the test refer exclusively to the object(s) mentioned

under point 1.1 of this report.

NSAI Certification TRANSPORT DEPARTMENT

TÜV Rheinland Kraftfahrt GmbH

Technologiezentrum Verkehrssicherheit Typprüfstelle Fahrzeuge/Fahrzeugteile Am Grauen Stein, D-51105 Köln (Poll)

Accreditation: NSAI-73 Am Grauen Stein, D-51105 Köln (Poll)

E24 16R-060086

Manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.

: HN-200-1



2. Test minutes

Type

Test facilities 2.1. : The test equipment used was in compliance with the requirements of

the directive/ regulation.

2.2. Test results : The type has been examined according to the amendments mentioned

in appendix 0.

An actual test of the type was not required. The results of the

previous tests are still valid.delete if unnecessary

Markings : The approval mark is marked clearly and indelibly.

2.3. General specifications : The components comply with the requirements of the directive/

regulation (see Appendix 1 for test results).

2.4. : The components comply with the special requirements of the Special requirements

directive/ regulation (see Appendix 1 for test results).

3. Remark concerning tested object(s) : All versions as stated in the information document are covered with

the tested version(s) and test object(s) respectively.

4. Appendices

0 List of modifications

1 Test protocol

Technical information about safety-belt L type according to Annex 1B for the communication of the ECE-type approval

> Information folder No. : HN-200-1 V00

5. Statement of conformity

The information folder and the type described there comply with the requirements in the above mentioned directive/ regulation.

The test laboratory is accredited for the above mentioned tests by the accreditation body of the NSAI, Motor Vehicle Type Approval, as the competent Administrative Department for the Ireland;

Accreditation Number: NSAI-73

The technical report comprises the pages 1 to 11 and shall not be reproduced except in full without the written approval of the test laboratory.

Engineering Center Guangdong, June.8, 2013

ZLJ

lough Any B.S.M.E. Liangjun Zhang

TÜV Rheinland Kraftfahrt GmbH



TÜV Rheinland Group Test Report No.: 87-R16-600/13

Type : HN-200-1

Manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.



LIST OF MODIFICATIONS APPENDIX 0

Correction of : ---

Modification of : ---

Addition of : ---

Deletion of : ---




TÜV Rheinland Kraftfahrt GmbH

Accreditation: NSAI-73

TÜV Rheinland Group Test Report No.: 87-R16-600/13

Type : HN-200-1





TEST PROTOCOL

APPENDIX 1

Paragraphs	Requirements and test description	Sample	Result of examination
6.1	General specifications		
	The belt or the restraint system is so designed and constructed that, when correctly installed and properly used by an occupant, its satisfactory operation is assured and it reduces the risk of bodily injury in the event of an accident. The straps of the belt are not liable to assume a dangerous configuration.		Complying
6.2	Rigid parts	<u> </u>	
6.2.1	General		
	The rigid parts of the safety-belt, such as buckles, adjusting devices, attachments and the like, have no sharp edges liable to cause wear or breakage of the straps by chafing.		Complying
	All parts of the belt assembly liable to be affected by corrosion are suitably protected against it. After undergoing the corrosion test prescribed in paragraph 7.2., no signs of deterioration likely to impair the proper functioning of the device or any significant corrosion is visible to the unaided eye of a qualified observer.		Complying
	Rigid parts intended to absorb energy or to be subjected to or to transmit a load are not fragile.	1,2	Complying
	The rigid items and parts made of plastics of a safety-belt are so located and installed that they are not liable, during every day use of a power-driven vehicle, to become trapped under a moveable seat or in a door of that vehicle.		Complying



TÜV Rheinland Kraftfahrt GmbH

Accreditation: NSAI-73



Type : HN-200-1

Manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.

6.2.2	Buckle		
6.2.2.1	The buckle is so designed to preclude any possibility of incorrect use. This means, inter alia, that it is not possible for the buckle to be left in a partially-closed condition. The procedure for opening the buckle is evident. The parts of the buckle likely to contact the body of the wearer present a section of not less than 20 cm ² and at least 46 mm in width, measured in a plane situated at a maximal distance of 2.5 mm from the contact surface.	5	Complying
6.2.2.2	The buckle, even when not under tension, remains closed whatever the position of the vehicle. It is not be possible to release the buckle inadvertently, accidentally or with a force of less than 1 daN. The buckle is easy to use and to grasp; when it is not under tension and when under tension, it is capable of being released by the wearer with a single simple movement of one hand in one direction; in addition, in the case of belt assemblies intended to be used for the front outboard seats, it is capable of being engaged by the wearer with a simple movement of one hand in one direction. The buckle can be released by pressing either a button or a similar device. The surface to which this pressure is applied has the following dimensions, with the button in the actual release position and when projected into a plane perpendicular to the button's initial direction of motion: for enclosed buttons, an area of not less than 4.5 cm ² and a width of not less than 15 mm; for non-enclosed buttons, an area of not less than 10 mm. The buckle release area is coloured red. No other part of the buckle is of this colour.	5	Complying
6.2.2.3	The buckle, when tested in accordance with paragraph 7.5.3, operates normally.	1,2	Complying
6.2.2.4	The buckle is capable of withstanding repeated operation.	1,2	Complying
6.2.2.6	The buckle has been tested for strength as prescribed in paragraphs 7.5.1. and, where appropriate, 7.5.5. It did not break, was not seriously distorted or became detached under the tension set up by the prescribed load (980 daN).		Complying
6.2.2.7	For the buckles which incorporate a component common to two assemblies, the strength and release tests of paragraphs 7.7. and 7.8. have also be carried out with the part of the buckle pertaining to one assembly being engaged in the mating part pertaining to the other, if it is possible for the buckle to be so assembled in use.		n.a.
6.2.3	Belt adjusting device	1	SARDS AUTHORIA
6.2.3.1	The belt after being put on by the wearer, adjust automatically to readily accessible to the seated wearer and is convenient and easy hand to suit the wearer's body size and the position of the vehicle	y to use. l	

TÜV Rheinland Kraftfahrt GmbH

Accreditation: NSAI-73

Technologiezentrum Verkehrssicherheit Typprüfstelle Fahrzeuge/Fahrzeugteile Am Grauen Stein, D-51105 Köln (Poll) page 6 of 11

Test Report No.: 87-R16-600/13



Type : HN-200-1

Manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.

6.2.3.2	Two samples of each belt adjusting device have been tested in accordance with the requirements of paragraph 7.3. The strap slip as shown did not exceed 25 mm for each sample of	4		f shifts : 1	
	adjusting device and the sum of shifts for all the adjusting devices did not exceed 40 mm.	5	Strap s Sum o	slip :20 f shifts : 20	0mm 0mm
6.2.3.3	All the adjustment devices have been tested for strength as prescribed in paragraph 7.5.1. They did not break or become detached under the tension set up by the prescribed load.	3	Complying		
6.2.3.4	During test in accordance with paragraph 7.5.6. the force required to operate any manually adjusting device did not exceed 5 daN.	4	Complying		
6.2.4	Attachments and belt adjustment devices for height.	3			n.a.
	The attachments have been tested for strength as prescribed in paragraphs 7.5.1. and 7.5.2. These parts did not break or became detached under the tension set up by the prescribed load.				
6.2.5	Retractors		1		
6.2.5.1	Requirements for manually unlocking retractors.	1,2	n.a.		
6.2.5.2	Requirements for Automatically locking retractors.	1,2			n.a.
6.2.5.2.1	The strap shall not move more than 30 mm between locking positions of the retractor before and after conditioning	1	After	Before: r After : n	
	according to 6.2.5.2.3.	2	Before After		mm mm
6.2.5.2.2	If the retractor is part of a lap belt, the retracting force of the strap shall be not less than 0.7 daN before and after conditioning according to 6.2.5.2.3.	1	a lap	Before:	daN daN
	If the retractor is part of an upper torso restraint, the retracting force of the strap shall be not less than 0.1 daN and not more than 0.7 daN before and after conditioning according to 6.2.5.2.3.	2	[]p		
	0.2.3.2.3.		upper	Before: After:	daN daN
			restra int		au (
6.2.5.3	Emergency locking retractors				
6.2.5.3.1.1 6.2.5.3.3	The locking occurred when the deceleration of the vehicle reached 0.45 g in the case of type 4 or 0.85g in the case of type	1			n.a.
	4N retractors. The amount of strap movement which occurred before the retractor locks did not exceed 50 mm before and after conditioning according to 6.2.5.3.5.	2			n.a. AUTHORITA
			1		NSAI Certification

TÜV Rheinland Kraftfahrt GmbH

Accreditation: NSAI-73

Technologiezentrum Verkehrssicherheit Typprüfstelle Fahrzeuge/Fahrzeugteile Am Grauen Stein, D-51105 Köln (Poll)

E24 16R-060086

TRANSPORT DEPARTMENT

page 7 of 11

Test Report No.: 87-R16-600/13



Type : HN-200-1

Manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.

6.2.5.3.1.2 6.2.5.3.3	It did not lock for values of acceleration of the strap measured in the direction of the extraction of the strap of less than 0.8 g in the case of type 4.	1,2		n.a.	
6.2.5.3.1.3 6.2.5.3.1.4 6.2.5.3.3	It did not lock when its sensing device was tilted 12° or less in any direction from the installation position specified by its manufacturer.	1		n.a.	
	It locked when its sensing device was tilted by more than 27° in the case of type 4 or 40° in the case of type 4N retractors in any direction from the installation position specified by its manufacturer.	2		n.a.	
6.2.5.3.1.5	The operation of a retractor depends on an external signal or power source.	1,2	n.a.		
6.2.5.3.2 6.2.5.3.3	During test in accordance with paragraph 7.6.2., the emergency locking retractor with multiple sensitivity, including strap sensitivity, complied with the specified requirements and also lock up when strap acceleration measured in the direction of	1		n.a.	
	unreeling was not less than 2.0 g. The amount of strap-movement which occurred before the retractor locks did not exceed 50 mm before and after conditioning according to 6.2.5.3.5.	2		n.a.	
6.2.5.3.4	If the retractor is part of a lap belt, the retracting force of the strap shall be not less than 0.7 daN before and after conditioning according to 6.2.5.3.5	1	[]part of a lap belt	n.a.	
	If the retractor is part of an upper torso restraint, the retracting force of the strap shall be not less than 0.1 daN and not more than 0.7 daN w before and after conditioning according to 6.2.5.3.5.	2	[] part of an upper torso restraint	n.a.	
6.2.6	Pre-loading device				
6.2.6.1	After corrosion testing in accordance with paragraph 7.2, the pre-loading device (including the impact sensor connected to the device by the original plugs but without any current passing through them) operates normally.	1,2	n.a.		
6.2.6.2	It has been verified that inadvertent operation of the device does not involve any risk of bodily injury for wearer.	1,2	n.a.		
6.2.6.3.1	After conditioning in accordance with paragraph 7.9.2, operation of the pre-loading device has not been activated by temperature and the device operates normally.	1,2	n.a.		
6.2.6.3.2	Precautions have been taken to prevent the hot gases expelled from igniting adjacent flammable materials.	1,2		n.a. AUTHORITA	
			•	NSAI R	

TÜV Rheinland Kraftfahrt GmbH

Accreditation: NSAI-73

Technologiezentrum Verkehrssicherheit Typprüfstelle Fahrzeuge/Fahrzeugteile Am Grauen Stein, D-51105 Köln (Poll)

E24 16R-060086

page 8 of 11

Certification
TRANSPORT
DEPARTMENT

Test Report No.: 87-R16-600/13



Type : HN-200-1

Manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.

6.3	Straps						
6.3.1.2 6.3.2 6.3.3	Strength after room-conditioning	Sample (Black color)	Condition		Breaking load of Strap (daN)	Percent of breaking load/dif erence (%)	Width of
	The breaking load of two straps samples conditioned in conformity with paragraph 7.4.1.1, determined as prescribed in paragraph 7.4.2., have been not less than 1,470 daN. The difference between the breaking loads of the two samples did not exceed 10 per cent of the greater of the breaking loads	1' 2'	room		2860 2840	0.7	47
	measured.	3'	light conditioning		2825	99.1	
	Strength after special conditioning In the case of the two strap samples conditioned in conformity	4'	condition	ing	2850	100	
	with one of the provisions of paragraph 7.4.1. (except 7.4.1.1.), the breaking load of the strap was not less than 75 per cent of average of the loads determined in the test referred to in paragraph 6.3.2. (Strength after room-conditioning) and not less than 1,470 daN.	5'	cold conditioning		2828	99.2	
		6'	condition		2820	98.9	
		7'	heat		2830	99.3	
		8'	condition	ing —	2768	97.1	
		9'	exposure of water		2808	98.5	
		10'	water		2818	98.9	
6.4.2.1	For both samples conditioned in compliance with paragraph 7.4.1.6, the breaking strength has been assessed as prescribed in paragraphs 7.4.2. and 7.5. It has been at least equal to 75 per cent of the breaking strength average determined during tests	Test procedur	Sampla	breakin load of Strap (daN)	perce	g load di	ercent of afference (%)
	breaking strength of the two samples have not exceeded 20 per cent of the highest measured breaking strength. For type 1 and type 2 procedures, the breaking strength test has been carried out on strap samples only (para. 7.4.2.). For type 3 procedure,	2 (Guide	(2)		n.a.		
		2 (Buckle	e 4	2790	97	.9	0.5
	the breaking strength test has been carried out on the strap in combination with the metal component involved (para. 7.5.).	loop)	5	2775	97	.4	0.0



TÜV Rheinland Kraftfahrt GmbH

Accreditation: NSAI-73

Test Report No.: 87-R16-600/13



Type : HN-200-1

Manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.

6.4	Belt assembly or restraint system						
6.4.1	Dynamic test						
6.4.1.2	The dynamic test has been performed on two belt assemblies which have not previously been under load. , except in the case of belt assemblies forming part of restraint systems when the dynamic test shall be performed on the restraint systems intended for one group of seats which have not previously been under load. The buckles of the belt assemblies to be tested have met the requirements of paragraph 6.2.2.4. above. In the case of safety belts with retractors, the retractor has been subjected to the dust resistance test laid down in paragraph 7.6.3.; in addition, in the case of safety belts or restraint systems equipped with a pre-loading device comprising pyrotechnic means, the device has been subjected to the conditioning specified in paragraph 7.9.2.						
6.4.1.2.1	The belts have undergone the corrosion test described in paragra 500 additional opening and closing cycles under normal conditional opening and cycles are cycles and cycles are cycles and cycles are cycles and cycles are cycles are cycles and cycles are cycles and cycles are c			buckles have	been subjected to		
6.4.1.2.2	Safety belts with retractors have been subjected to the tests described in paragraph 6.2.5.2. or to those described in paragraph 6.2.5.3. If, however, a retractor has already been subjected to the corrosion test in accordance with the provisions of paragraph 6.4.1.2.1., above, this test has not repeated.						
6.4.1.2.3	In the case of a belt intended for use with a belt adjustment device for height, as defined in paragraph 2.9.6. above, the test has been carried out with the device adjusted in the most unfavourable position(s) chosen by the technical service responsible for testing.						
6.4.1.2.4	In the case of safety belt with a preloading device the minimum displacement specified in paragraph 6.4.1.3.2. may be reduced by half. For the purpose of this test, the preloading device has been in operation.						
6.4.1.3	During this test, the following requirements shall be met:						
6.4.1.3.1	No part of the belt assembly or a restraint system affecting the restraint of the occupant did break and no buckles or locking system or displacement system did release or unlock;		Complying				
6.4.1.3.2 6.4.1.3.3 6.2.2.5	of other types of belts, the forward displacement shall be		pelvic level (mm)	chest level (mm)	force to open the buckle after test (daN)		
	between 80 and 200 mm at pelvic level and between 100 and 300 mm at chest level. In the case of a harness belt or safety belt with a preloading device, the minimum displacements specified above may be reduced by half. In the case of a safety belt intended to be used in an outboard front seating position protected by an airbag in front of it, the displacement of the chest reference point may exceed that		100	-	3.7		
	specified in paragraph 6.4.1.3.2. above if its speed at this value does not exceed 24 km/h. (worst case)						
	The force required to open the buckle in the test as prescribed in paragraph 7.8. shall not exceed 6 daN.	2	100	- ANDAR	3.8		
6.4.1.4	In the case of a restraint system			in a	NSAI E		
					RANSPORT		

Accreditation: NSAI-73

page 10 of 11

TÜV Rheinland Group Test Report No.: 87-R16-600/13

Type : HN-200-1

Manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.



Technical information about safety-belt type according to Annex 1B for the communication of the ECE-type approval

Appendix L

1. Restraint system : (with) /three-point belt/ lap belt/-special type

belt/ fitted (with) energy absorber/ retractor/ device for height adjustment of the upper pillar

loop (2)

2. Trade name or mark : Hazna

3. Manufacturer's designation of the type

of belt or restraining system

: HN-200-1

Manufacturer's name 4. : Danyang Hazna Vehicle Parts Co., Ltd.

5. If applicable, name of his representative : n.a.

6. Address : Fangnan Village, Fangxian Town, Danyang City,

Jiangsu Province, China

7. Submitted for approval on : May. 25, 2013

8. Technical service responsible for

conducting approval tests

: TÜV Rheinland Kraftfahrt GmbH

Technologiezentrum Verkehrssicherheit Typprüfstelle Fahrzeuge/Fahrzeugteile

Am Grauen Stein D-51105 Köln (Poll)

9. Date of test report issued by that service : June.8, 2013

10. Number of test report issued by that

service

: 87-R16-600/13

: deceleration / acceleration (1) 11. Type of device

: granted/refused/withdrawn (1) for general use /for 12. Approval

use in a particular vehicle or in particular types

of vehicles (1) (3)

13. Position and nature of the marking : Label sewed on long end assembly



Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province, China

PARTIAL MODEL INFORMATION DOCUMENT NO.: HN-200-1 V00

according to ECE-Regulation

UNIFORM PROVISIONS CONCERNING THE APPROVAL OF SAFETY-BELTS, RESTRAINT SYSTEMS, CHILD RESTRAINT SYSTEMS AND ISOFIX CHILD RESTRAINT SYSTEMS FOR OCCUPANTS OF POWER-DRIVEN VEHICLES

ECE-R16

Including all amendments until Series of amendments : 06

Type: HN-200-1

This model information document consists of page 1 to 11



Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province, China Info. Doc. No: HN-200-1 V00

Issue Date: May 25, 2013

Content of attachment Subject Drawing No.

Safety belt and buckle assembly HN-200-1

Webbing Color Overview

Adjusting Buckle tongue

HN-200-1-001

Plate anchor

HN-200-1-002

Label

HN-200-1-003

Buckle head

HN-200-1-004

Position of safety belt anchorages

Refer to Page 11

Information document in respect of safety-belt

0. GENERAL

0.1. Make (trade name of manufacturer) : Hazna

0.2. Type and general commercial description(s) : HN-200-1

0.5. Name and address of manufacturer : Danyang Hazna Vehicle Parts Co., Ltd.

Fangnan Village, Fangxian Town, Danyang City,

Jiangsu Province, China

0.7. Location and method of affixing of the approval

mark

: Label sewed on the belt,

Refer to drawing no.: HN-200-1

0.8. Name and address(es) of assembly plant(s) : Danyang Hazna Vehicle Parts Co., Ltd.

Fangnan Village, Fangxian Town, Danyang City,

Jiangsu Province, China

1. LIST OF VEHICLE(S)TO WHICH THE

DEVICE IS INTENDED TO BE FITTED (if

applicable)

Can be used in vehicles conforming to

installation positions of page 11

Location : Outboard seat positions other than front and

center seating positions

2. DESCRIPTION OF THE DEVICE

2.1. Safety belt



Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province, China Info. Doc. No: HN-200-1 V00

Issue Date: May 25, 2013

2.1.1. Configuration of safety belt : 2-point lapbelt

Longest length of webbing : $1200 \pm 30 \text{mm}$

2.1.2. Details of webbing

Long end assembly

Material : Polyester, Piece Dyed

Weave : 5 Panel
Thickness : 1.15-1.2mm
Width : 46-49mm
Color : Black

Buckle Assembly

Material : Polyester, Piece Dyed

Weave : 5 Panel
Thickness : 1.15-1.2mm
Width : 46-49mm
Color : Black

2.1.3. Retractor Not applicable

Designation : /
Type : /

2.1.3.1. Additional information : Not applicable

2.1.4. Drawings of the rigid parts : Refer to drawing no.

HN-200-1, HN-200-1-002

2.1.5. Diagram of the safety belt assembly enabling : Refer to drawing no.

identification and location of the rigid parts HN-200-1

2.1.6. Mounting instructions showing, inter alia, the : Refer to drawing no.

installation of the retractor and its sensing device HN-200-1

2.1.7. Device for adjusting the height : Not applicable

Travel

Number of positions

2.1.8. Pre-loading device or system : Not applicable

All fire No fire Resistance



Danyang Hazna Vehicle Parts Co., Ltd. Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province, China

Info. Doc. No: **HN-200-1 V00**

Issue Date: May 25, 2013

•		
	Monitor current	
	Temperature	
2.2.	Restraint system	
	In addition to the information required in 2.1 above	
2.2.1.	Drawings of the relevant parts of the vehicle structure and any seat anchorage reinforcements(1)	: Not applicable
2.2.2.	Drawings of the seat, showing its structure, adjustment system and fixing components, with an indication of the materials used(1)	: Not applicable
2.2.3.	Drawing or photograph of the restraint system as installed(1)	: Not applicable
2.2.	Restraint system	: Not applicable
	In addition to the information required in 2.1 above	
2.3.	Child restraint system	
2.3.1.	Category(ies) (1)	: Not applicable
2.3.2.	Mass group(s) (1)	: Not applicable
2.3.3.	Forward-facing child restraint/rearward-facing child restraint/carry-cot (1)	: Not applicable
2.3.4.	Integral/non-integral/partial/booster cushion (1)	: Not applicable
2.3.5.	Belt type: (adult) three-point belt/(adult)lap belt/special type belt/retractor (1)	: Not applicable
2.3.6.	Other features: chair assembly/impact shield (1)	: Not applicable
2.3.7.	Drawings, diagrams and plans of the child restraint, including any retractor, chair assembly, impact shield fitted(1)	: Not applicable
2.3.8.	Declaration on toxicity(1)	: Not applicable
2.3.9.	Declaration on flammability(1)	: Not applicable

Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province, China Info. Doc. No: HN-200-1 V00

Issue Date: May 25, 2013


Note: This seat belt is not made up of materials with properties of Polyamide 6 as regards water retention. These materials are prohibited in all mechanical parts for which such a phenomenon is likely to have an adverse effect on their operation.



Danyang Hazna Vehicle Parts Co., Ltd. Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province, China

Info. Doc. No: **HN-200-1 V00**

Issue Date: May 25, 2013




Danyang Hazna Vehicle Parts Co., Ltd. Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province, China

Info. Doc. No: **HN-200-1 V00**

Issue Date: May 25, 2013


Straps color overview




Black color




Info. Doc. No: HN-200-1 V00



Info. Doc. No: HN-200-1 V00




Info. Doc. No: **HN-200-1 V00**



Danyang Hazna Vehicle Parts Co., Ltd. Fangnan Village, Fangxian Town, Danyang City, Jiangsu Province, China

Info. Doc. No: **HN-200-1 V00**

Issue Date: May 25, 2013




Drawing No.: HN-200-1-003



Info. Doc. No: **HN-200-1 V00**

SEAT BELT ANCHORAGE DETAILS



	"X" - Axis	"Y" - Axis	"Z" - Axis
Buckle	50	230	-210
Lower anchorage	180	-240	-160

